



Increase Knowledge

Establish Credibility

Learn Hands On

Increase Home Sales

Introduction

.



Bruce Kelly

- President of a Local Inspection Company
 - ASHI Inspector
 - **NEHA** Certified
 - **EDI** Certified


- **Real Estate License**
- **Started Inspections in 1990**
- Licenses held for inspection company
- **Pilots License**
- Hometown
- Attended CMSU and attained my Bachelor's degree from William Jewell College
- Second Generation Builder
 - **Owned and Operated a Residential and Commercial Construction Company for 23 Years**


Table of Contents



















































































































EXECTOR Problems with Synthetic Stucco.

Improper Installation.


Bottom edge of stucco embedded in soil allow termites to burrow through to wall cavity.


Lack of flashing around windows and doors allows moisture to enter wall cavity.

Lack of sealant around penetrations, light fixtures, receptacles, etc.

Gutters allowing water to drain onto the stucco.















Don't Let LP or Masonite Siding Ruin Your Deal!


•Find out if a claim has been filed

Have siding inspected for condition

Inform client of normal maintenance procedures

EXERNE Class Action Lawsuits


- Several class action lawsuits are taking place throughout the country involving different composition board manufactures.
- Louisiana-Pacific <u>www.lpsiding.com</u> or 800-648-6893
- Georgia-Pacific Corporation 888-882-5246
- Masonite Corporation <u>www.kinsella.com/masonite</u> or 800-330-2722




































Sources of interior water damage







plumbing leaks




melting snow



accidental spills




ice damming and condensation




air conditioning leaks

roof or flashing leaks




door leaks



wall, window, solarium and skylight leaks






























Plumbing









Plumbing







Problems With Polybutylene

73

•Oxidants in the public water supply, especially chlorine react with the piping and fittings causing the pipe to become brittle

Brittleness causes the pipe to become weak and susceptible to sudden failure

Improper installation also leads to problems

Plastic and metal fittings both fail due to improperly calibrated crimping machines, but plastic fails at a greater rate

Failure takes 10-15 years in most cases

The piping will deteriorate from the inside, so a visual inspection cannot determine if the piping is in good condition







Plumbing <u>CLASS ACTION SUIT</u> <u>COX VS. SHELL OIL</u>


- ♦ In 1995 manufacturers agreed to pay at least \$950 MM.
- You must own or have previously owned a dwelling plumbed with polybutylene or have had PB yard service.
- The polybutylene must have been installed between January 1, 1978 and July 31, 1995.
- Interior polybutylene must have been installed with PB pipe and the insert fittings.
- To obtain a claim eligibility form, call *1-800-392-7591 or visit www.pbpipe.com*

Leaks occurring <u>after August 21, 1995</u> in PB piping


Dwelling Type		Leak Must Occur Within	Must be Filed Within
Mobiles homes		10 years of PB yard service line installation	11 years of PB yard service line installation
Yard Service		10 years of PB yard service line installation	11 years of PB yard service line installation
Single Family Plastic Fittings	w/	13 years of PB plumbing installation	14 years of PB plumbing installation
Single Family Metal Fittings	w/	16 years of PB plumbing installation or January 31, 2009 (whichever comes first)	17 years of PB plumbing installation or May 1, 2009 (whichever comes first)













































































































Heating





















Factors affecting air supply




























Air Movement













Flow of cooled air - modern ductwork





Flow of cooled air - older-style ductwork










Where is the insulation?













Other types of polystyrene insulation

































Differences between old and new construction












Two comfort strategies









Exhaust fan conditions

